

FIG. 1A




FIG. 1B

SHAPING PERIPHERIES

FIG. 1C




FIG. 4A




FIG. 4B

SHAPING PERIPHERY

FIG. 4C




FIG. 1A

2/4

FIG. 2A




FIG. 2B




FIG. 2C



FIG. 3A





FIG. 3B



NOT AVAILABLE COPY

3/4

FIG. 5 A




FIG. 5 B




FIG. 5 C




FIG. 6 A





FIG. 6 B



BEST AVAILABLE COPY

00000000-0000-0000-0000-00000000

FIG. 7





FIG. 8A




PROVISIONAL MOLDING

FIG. 8B

SHAPING PERIPHERY
APPLYING ADHESIVE

FIG. 8C



SIMULTANEOUS MOLDING

BEST AVAILABLE COPY